INSTALLATION INSTRUCTIONS FOR 1291-580 1292-580 1293-580

For Wall Mount Fixture

CMinka Lighting, Inc.

This product is protected by United States Federal and/or State Law, including Patent and/or Copyright laws.

WARNING! SHUT POWER OFF AT FUSE OR CIRCUIT BREAKER. AVERTISSEMENT! COUPER LE COURANT AU NIVEAU DES FUSIBLES OU DU DISJONCTEUR.

MOUNTING THE FIXTURE

Installation (see fig.1)

- 1. Disconnect power at main electrical panel before installation.
- Thread the nipple part way into the center hole of the crossbar and secure with hex nut.
- Attach the crossbar to the junction box using two junction box screws. The side of the crossbar marked "GND" must face out.
- Follow wiring instructions carefully (see fig.2)
- Feed the nipple through the hole of the tamp body (D), screwing the cap nut (E) from the face side to secure the nipple to the fixture. Turn the cap nut and nipple to thread the nipple into the center hole of the crossbar and lock the lamp body (D) using the cap nut (E).
- 6. Place the glass shade (C) and the check ring (B) onto the socket of the fixture body (D), then securely tighten the check ring (B)using the sleeve (A). (The sleeve (A) is a tool, when the installation is complete, it must be taken away.)
- 7 install the light bulbs (not included) in accordance with the fixture's specifications: DO NOT EXCEED THE MAXIMUM WATTAGE RATING! (NE PAS DEPASSER LA PUISSANCE NOMINALE MAXIMALE!).

Wiring (see fig.2)

- Connect the electrical wires as follows. Connect the Black wire from the fixture to the black house (hot) Wire. Connect the white wire from the fixture to the white (neutral) house wire. Make sure all wire nuts are secured. You may wrap the connections with electrical tape. If your outlet box has a ground wire (green or bare copper) connects fixture's ground wire to it. Otherwise attach the bare copper fixture wire to the green ground screw on the crossbar.
- Tuck the wire connections neathy into the wall junction box.







